| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|-------|---|---|---------------------|---------|------------------|
| S1 | 10387 | check near2 valv\$2 | US-PGPUB | OR | OFF | 2005/07/06 10:58 |
| S2 | 2946 | check near2 valv\$2 and engin\$2 | US-PGPUB | OR | OFF | 2005/07/05 12:09 |
| S3 | 345 | check near2 valv\$2 and engin\$2 and (crankcase or crank near2 case) | US-PGPUB | OR | OFF | 2005/07/05 12:10 |
| S4 | 345 | check near2 valv\$2 and engin\$2 and (crankcase or crank near2 case) and valv\$2 | US-PGPUB | OR | OFF | 2005/07/05 12:11 |
| S5 | 379 | (check or ball\$2) near2 valv\$2 and engin\$2 and (crankcase or crank near2 case) and valv\$2 | US-PGPUB | OR | OFF | 2005/07/05 12:17 |
| S6 | 68 | ball\$2 near2 valv\$2 and engin\$2 and (crankcase or crank near2 case) and valv\$2 | US-PGPUB | OR | OFF | 2005/07/05 12:48 |
| S7 | 68 | ball\$2 near2 valv\$2 and engin\$2 and (crankcase or crank near2 case) and valv\$2 | US-PGPUB | OR | OFF | 2005/07/05 12:48 |
| S8 | 510 | ball\$2 near2 valv\$2 and engin\$2 and (crankcase or crank near2 case) and valv\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 12:56 |
| S9 | 563 | ball\$2 near2 (valv\$2 or check) and engin\$2 and (crankcase or crank near2 case) and valv\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 15:57 |
| S10 | 1651 | 123/196R.ccls. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 15:57 |
| S11 | 47 | 123/196R:ccls. and ball near2 valv\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:18 |
| S12 | 1 | "6394060" and ball\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 16:06 |
| S15 | 26 | "4404936" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 16:47 |

| S16 | 0 | "6394060" and gasket\$2 | US-PGPUB | OR | OFF | 2005/07/06 10:58 |
|-----|-----|--|---|----|-----|------------------|
| S17 | 0 | "6394060" and (gasket\$2 or seal\$2) | US-PGPUB | OR | OFF | 2005/07/06 10:58 |
| S18 | 0 | "6394060" and (gasket\$2 or seal\$2 or grommet\$2) | US-PGPUB | OR | OFF | 2005/07/06 10:59 |
| S19 | 490 | 123/196R.ccls. and (gasket\$2 or seal\$2 or grommet\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 11:00 |
| S20 | 124 | 123/196R.ccls. and (gasket\$2 or seal\$2 or grommet\$2) same crankcase and cylinder near2 head | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 11:24 |
| S21 | 5 | 123/196R.ccls. and head near2 gasket\$2 same crankcase and cylinder near2 head | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 11:34 |
| S22 | 122 | head near2 gasket\$2 same crankcase and cylinder near2 head not S20 not S21 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:06 |
| S23 | 190 | 123/196R.ccls. and check near2 valv\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:19 |
| S24 | 0 | 123/196R.ccls. and check near2 (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:23 |
| S25 | 104 | 123/196R.ccls. and (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:28 |
| S26 | 0 | 123/196M.ccls. and check near2 (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:23 |
| S27 | 0 | 123/196W.ccls. and check near2 (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:23 |

| S28 | 0 | 123/196P.ccls. and check near2 (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:33 |
|-----|-------|---|---|----|-----|------------------|
| S29 | 0 | 123/196S.ccls. and check near2 (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:23 |
| S30 | 0 | 123/196R.ccls. and fluorocarbon . | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:57 |
| S31 | 0 | 123/196R.ccls.: and fluorocarbon\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:28 |
| S32 | 1 | "123"/\$.ccls. and fluorocarbon\$2 near2 valv\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:29 |
| S33 | 1 | 123/196CP.ccls. and check near2 (disk\$2 or disc\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:38 |
| S34 | 45337 | fluorocarbon | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:53 |
| S35 | 1624 | fluorocarbon and engine | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 13:53 |
| S37 | 16 | 123/196R.ccls. and ceramic\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 14:01 |
| S38 | 170 | "123"/\$.ccls. and ceramic\$2 near2 valv\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 14:09 |

| S39 | 2 | "123"/\$.ccls. and ceramic\$2 near2 (check near2 valv\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 15:46 |
|-----|-----|--|---|----|-----|------------------|
| S40 | 1 | 10/642374 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 15:49 |
| S41 | 1 | 10/642374 and bore | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 16:12 |
| S42 | 1 | 10/642374 and "172" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 18:33 |
| S43 | 4 | "6394060" and pressur\$9 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/06 18:33 |
| S44 | 8 | "123"/\$.ccls. and plastic\$2 near2 (check near2 valv\$2) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:05 |
| S45 | 251 | plastic\$2 near2 (check near2 valv\$2) not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:13 |
| S46 | 12 | plastic\$2 near2 (check near2 valv\$2) and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:20 |
| S47 | 0 | plastic\$2 near2 (check or ball) near2 valv\$2 same crankcase and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:21 |
| S48 | 19 | plastic\$2 near2 (check or ball) near2 valv\$2 and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:22 |

| S49 | 447 | plastic\$2 near2 valv\$2 and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:22 |
|-----|-----|--|---|------------|-----|------------------|
| S50 | 0 | plastic\$2 near2 valv\$2 same crank near2 case and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:23 |
| S51 | 13 | plastic\$2 near2 valv\$2 same crankcase and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:39 |
| S52 | 17 | "5067449" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:34 |
| S53 | 5 | "5067449" and plastic\$2 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | O R | OFF | 2005/07/07 16:34 |
| S54 | 28 | plastic\$2 near2 valv\$2 same oil and engine not S44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:57 |
| S55 | 43 | plastic\$2 near2 ball\$2 same valv\$2 and engine not S 44 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:42 |
| S56 | 42 | plastic\$2 near2 ball\$2 same valv\$2 and engine not S44 not S51 not S54 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 18:45 |
| S57 | 1 | plastic\$2 near3 positive near2 crankcase near2 ventilation | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:55 |
| S58 | 0 | plastic\$2 near2 valv\$2 same oil and engine not S44 not S54 not S56 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:57 |

| S59 | 409 | plastic\$2 near2 valv\$2 and engine not S44 not S54 not S56 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 16:58 |
|-----|-----|--|---|----|-----|------------------|
| S60 | 16 | "4579092" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 18:46 |
| S61 | 8 | "5611301" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/07 18:46 |